

Yellow / Purple Glazes – Cone 03-06

Kim's Yellow cone 05

White Lead.....	60
Frit 3124.....	20
Flint.....	20
Tin ox.....	1
Yellow Lead Chromate.....	1

30. Glaze VI 05 Variation

Gerstley Borate	53
Whiting	6.9
Zinc Oxide	5.5
EPK	8.9
Flint	25.7
Bentonite	2
Rutile	.4
Tin Oxide	5

Clear Yellow Glaze (Cone 03)

Barium Carbonate.....	14%
Gerstley Borate.....	34
Potash Feldspar.....	37
Flint.....	15

100%

Add: Black Iron Oxide..... 8%

Ball-mill the black iron oxide for at least eight hours.

#12 Shiny Cream Tan (Utah)

3134	75
Ball Clay	10
Zirconia	15
Rutile	15

14 RSTH SATIN MATT BASE 67-02		
GB	32	CRAZ CERATE 1
LC	9	YELLOW - YELSTONE 2
W	17	
Zr	4	
EPK	4	LIGHT & LWE
	35	CUPPER CARB 1.5
Bent	2	

Gerstley Borate Base Glaze Cone 03

Gerstley Borate.....	55%
EPK (Edgar Plastic Kaolin).....	30
Silica (Flint).....	15
	100%

Base Colorants:

<i>Blue</i>	
Cobalt Oxide.....	2.0%
<i>Rich Green</i>	
Copper Carbonate	6-8%
<i>Rich Yellow</i>	
Rutile	6-8%

Clear Tan Glaze

(Cone 06)

Gerstley Borate	70%
Cedar Heights Redart	30
	100%

* Honey Clear Glaze

- Gerstley Borate	380g
- Potash Feldspar (custer)	370g
- Barium Carb.	140g
- Flint	110g
- Black Iron Ox	80g
- Bentonite	10g

Pink Purple Spots 3 cone 04 ox/

Gerstly Borate.....45
Zinc ox.....5
Custer.....45
Flint.....5
Add: Color Mixture 1.....3%
Semi-Glossy, Opaque.

Color Mixture 1

Tin ox.....50
Copper carb.....7.5
Flint.....22.5
Silicon carb.....20

Pink Purple Spots 2 cone 04 ox/

Gerstly Borate.....50
Zinc ox.....5
Custer.....40
Flint.....5
Add: Color Mixture 1.....3%
Semi-Matte, Opaque.

Pink Purple Spots 1 cone 04 ox/

Gerstly Borate.....50
Zinc ox.....5
Custer.....30
Flint.....15
Add: Color Mixture 1.....3%
Matte, Opaque.

Wilson's Purple Aqua Patina
(Cone 06)

Barium Carbonate	45 parts
Nepheline Syenite	45
Frit 3289 (Ferro)	4
Copper Carbonate	4-8
Bentonite	2
	100-104 parts

Periwinkle

Cone 04

used by Trevor Youngberg

Ferro Frit #3195	47.26%
Ferro Frit #3124	37.81
EPK	11.34
Tin Oxide	2.84
Copper Carbonate	.47
Cobalt Oxide	.28

TOTAL: 100.00%

Clear Purple Glaze

(Cone 03)

Barium Carbonate	1.5%
Gerstley Borate	7.3
Potash Feldspar	2.0
Edgar Plastic Kaolin	6.7
Frit 3110 (Ferro)	72.5
Flint	10.0
	100.0%
Add: Cobalt Sulfate	0.3%
Manganese Carbonate ..	3.0%